

HABS,
NH,
7-BOSC,
1-

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

Penacook House
(Bonney Tavern)
Boscawen
Merrimack County
New Hampshire

HABS No. NH-25

Photographs NH-25-1 through NH-25-8 were taken by John C. Fletcher in May 1937. Photographs NH-25-9 through NH-25-79 were taken by R. A. Waugh, also in May 1937.

- NH-25-1 SOUTH ELEVATION OF MAIN HOUSE
- NH-25-2 SOUTHWEST ELEVATION SHOWING ELL TO THE NORTH
- NH-25-3 WEST ELEVATION OF ELL AND SHED
- NH-25-4 NORTHEAST ELEVATION SHOWING ELL AND SHED
- NH-25-5 EAST ELEVATION OF HOUSE AND SHEDS
- NH-25-6 EAST ELEVATION SHOWING APPENDAGES TO THE NORTH
- NH-25-7 EAST ELEVATION SHOWING WING ON ELL
- NH-25-8 SOUTH ELEVATION SHOWING ROUGH BOARDINGS AND FRAMING
- NH-25-9 CUT IN SOUTH SILL FOR EARLIER DOOR
- NH-25-10 SOUTH ELEVATION DOOR FRAMING FIRST FLOOR SOUTH (NOTE CUT FOR NEW DOOR IN BRACE)
- NH-25-11 EAST ELEVATION SHOWING CUTS IN ROUGH BOARDING FOR CELLAR BULK-HEAD FRAMING
- NH-25-12 SOUTHEAST CORNER POST SECOND FLOOR SHOWING BOARDING
- NH-25-13 EXTERIOR SECOND FLOOR SOUTHEAST BEDROOM SHOWING FRAMING AND BRACING
- NH-25-14 FRAMING MARKING ON INTERMEDIATE POST AND BRACING ON SOUTH ELEVATION SECOND FLOOR
- NH-25-15 SECOND FLOOR SOUTH EAST CORNER POST SHOWING MORTISE FOR PORCH
- NH-25-16 SOUTHWEST ELEVATION SHOWING ROUGH BOARDING ON MAIN HOUSE AND ELL
- NH-25-17 FIRST AND SECOND FLOOR FRAMING SOUTHWEST CORNER POST

PENACOOK HOUSE
(Bonney Tavern)
HABS No. NH-25
Index to Photographs
(Page 2)

NH-25-18	SOUTHWEST CORNER POST
NH-25-19	DETAIL OF SOUTHWEST CORNER SILL
NH-25-20	NORTHEAST CORNER OF SILL
NH-25-21	END OF INTERMEDIATE POST
NH-25-22	INTERMEDIATE POST NORTH ELEVATION
NH-25-23	INTERMEDIATE POST SECOND FLOOR WEST ELEVATION
NH-25-24	INTERMEDIATE POST EAST WALL FRAME OF HALL FIRST FLOOR
NH-25-25	INTERMEDIATE HALL POST, SECOND FLOOR, WEST
NH-25-26	MARKING ON SUMMER BEAM SOUTH WEST ROOM, SECOND FLOOR
NH-25-27	SOUTH ELEVATION OF CELLAR WALL, SOUTH SILL, AND HALL GIRT
NH-25-28	WEST ELEVATION OF CELLAR WALL, SHOWING HALL GIRTS AND JOG IN CELLAR DOOR STAIR
NH-25-29	SOUTH ELEVATION OF CELLAR WALL SHOWING CLAY BEDDING IN WALL
NH-25-30	SOUTH ELEVATION OF CELLAR WALL SHOWING CLAY BEDDING IN WALL
NH-25-31	SOUTHWEST CORNER SHOWING CELLAR WALL CONSTRUCTION
NH-25-32	EAST CHIMNEY BASE LOOKING EAST SHOWING CONTINUOUS LOG FOUNDATION OVER VAULT
NH-25-33	EAST CHIMNEY BASE LOOKING EAST ON CONTINUOUS LOG FOUNDATION
NH-25-34	SOUTHWEST CORNER OF EAST CHIMNEY BASE SHOWING VAULT AND FRAME
NH-25-35	SOUTHWEST CORNER OF EAST CHIMNEY BASE SHOWING CONTINUOUS LOG FOUNDATION OVER VAULT AND THE WEST CRIBBING LOG WITH STONE FILL ON THE EAST.
NH-25-36	STONE HEARTH IN SOUTHEAST ROOM, FIRST FLOOR
NH-25-37	JAMB DETAIL OF NORTHEAST ROOM FIRST FLOOR MAIN HOUSE SHOWING EARLIER JAMB IN RELATION TO PRESENT FRANKLIN STOVE
NH-25-38	DETAIL OF CHIMNEY HAUNCH NORTHEAST BEDROOM SECOND FLOOR LOOKING SOUTH

PENACOOK HOUSE
(Bonney Tavern)
HABS No. NH-25
Index to Photographs
(Page 3)

NH-25-39	CHIMNEY HAUNCH IN SECOND FLOOR NORTHEAST BEDROOM LOOKING SOUTH
NH-25-40	FLOOR TIMBER IN ATTIC OVER HALL AND NORTHEAST ROOM
NH-25-41	ATTIC FLOOR MAIN HOUSE SMALL TIMBERS DOVE-TAILING INTO INTERMEDIATE GIRT
NH-25-42	NORTHEAST CORNER POST AND ATTIC FLOOR GIRT (NOTE BLOCKING FOR CORNICE)
NH-25-43	EAST ATTIC FLOOR GIRT
NH-25-44	INTERMEDIATE ATTIC FLOOR GIRT NORTH ELEVATION
NH-25-45	INTERMEDIATE FLOOR POST AND ATTIC FLOOR GIRT NORTH ON MAIN HOUSE
NH-25-46	NORTH ELEVATION HALL GIRT ATTIC FLOOR
NH-25-47	ATTIC FLOOR GIRT
NH-25-48	UPSIDE DOWN VIEW ATTIC FLOOR GIRT
NH-25-49	MORTISE FOR QUEEN POST ATTIC FLOOR
NH-25-50	SOUTHEAST CORNER MAIN RAFTER AND PLATE
NH-25-51	QUEEN POST AND BRACING MAIN HOUSE
NH-25-52	BOTTOM OF QUEEN POST
NH-25-53	TOP OF QUEEN POST
NH-25-54	PURLIN MAIN ROOF
NH-25-55	PURLIN MAIN ROOF
NH-25-56	DIAGONAL BRACE IN ROOF FRAMING ON NORTH
NH-25-57	RIDGE MAIN HOUSE
NH-25-58	MAIN HOUSE RIDGE POLE
NH-25-59	TYPICAL WINDOW EAST ELEVATION FIRST FLOOR
NH-25-60	WINDOW SHUTTERS IN EAST ROOM FIRST FLOOR SOUTH ELEVATION
NH-25-61	WRITING FOUND ON INTERIOR BOARDING UNDER ATTIC STAIRS ON WEST WALL

PENACOOK HOUSE
(Bonney Tavern)
HABS No. NH-25
Index to Photographs
(Page 4)

- NH-25-62 CLOSE UP OF WRITING FOUND ON INTERIOR BOARDING UNDER ATTIC STAIRS ON WEST WALL
- NH-25-63 STENCIL DESIGN ON PLASTER WEST WALL SOUTHEAST BEDROOM SECOND FLOOR ON SOUTH ELEVATION
- NH-25-64 BACK OF PANELING IN DADO IN HALL
- NH-25-65 MARKINGS ON IRON LINTEL FROM KITCHEN FIREPLACE IN ELL
- NH-25-66 MANTEL OF FIREPLACE IN FIRST FLOOR NORTHWEST BEDROOM IN ELL
- NH-25-67 INTERMEDIATE POST ON KITCHEN (ELL) ON EAST ELEVATION
- NH-25-68 FIRST FLOOR OF ELL FRAMING LOOKING NORTHWEST (NOTE EXCAVATED AND UNEXCAVATED PORTION)
- NH-25-69 LOOKING DOWN FROM NORTH SECOND FLOOR GIRT ON FRAMING OF ELL FIRST FLOOR INTO MAIN HOUSE
- NH-25-70 ELL ROOF FRAMING JOINING TO MAIN HOUSE
- NH-25-71 GABLE WING FRAMING ON ELL AND ELL ROOF FRAMING
- NH-25-72 ROOF FRAMING IN ELL LOOKING NORTH
- NH-25-73 MAIN RAFTER AND PLATE WEST ELEVATION OF ELL
- NH-25-74 GENERAL ATTIC FLOOR FRAMING IN ELL
- NH-25-75 BRACING IN ATTIC FLOOR AT INTERMEDIATE (WEST) IN ELL
- NH-25-76 SOUTH ELEVATION OF SHED ON ELL (NOTE FRAMING)
- NH-25-77 SASH FOUND IN SHED NORTH ELEVATION (NOTE MUTINS)
- NH-25-78 WEST ELEVATION OF SHED ON EAST OF MAIN HOUSE
- NH-25-79 SOUTH ELEVATION OF SHED ON EAST OF MAIN HOUSE